Approved For Release	2002/06/13:	CIA-RDP69B	00041R00	150 002 0016-4

BLACK SHIELD CHARGELIST (as of 23 Dec 1967)

Mission RX 6843
Msn Date 5 JANGS

H-hr 057 02302 1130 L ATD 1130 L L-hr 057 0630 2 1530 L ATA /539 L Page 2 of 2

	Msn Date 5 JAN 68 L-hr 057 0630	4.152	e. A.				
5 X:1 As	inds Action		Rspb1 Indiv		Due (L)	Done (L)	Intls
	Send rminals & Top-Off AR Forecasts]	B-5	В	1630	05/ 0130	0035	54
0.00	the same and the same and	B-25	В			2055	51
-9:00		B-11	В	1730		I	TY
9:00		B-12	Z			0300	JH .
8:30	Prepare met watch log forms for use in CP Complete slides & prepare flimsy masters for TTFC	B-24	В	1800	0300	0230	74
X:\$A		B-12	z	1800	0300	0500	
	Plot 1200Z RODN & AR vicinity RAOBs		z	1900			W.
	Plot & any pertinent 30mb data on map for festr		A,B,C				
-8:00	Send Hazardous Wx Advisory] if needed; thru Lhr			1900		0400	Della
-7:30	Appraise TTFC slides & flimsy masters; run off copies	D=24	-	1700	0700	7,00	
5X1A	Give TTFC mission briefing & 175 data to: (Top-Off AR wx scout & s	B-24	C	7185	1605	0615	DEK
		D 06	1		l .	1 1	
	(1st cell, distant AR)	B-24	C	3/15	0615	0630	Dels
	(2nd cell, distant AR)AR	B-24	С				
	AR AR	B-24	С	2215	0815	0830	Dak
	(IOP=OII PLINALY)			K315	0017	<i>1000</i>	Pals
	(Other AR, strip alert, etc.)	B-24	С			ļ	
5X1A					ļ <u>.</u>		
-5: 00	Prepare RODN & Top-Off AR forecasts	B-5	С	2130	0630	0630	DEB
-4:00	Send [Terminals & Top-Off AR Forecasts]	B-5	С	2230	0730	0650	Dils
-4:00	Send [Met Watch Observations]	B-18	Z.	2230	0730	0715	JH
-3:45	Plot 1800Z RODN & AR RAOBs, temp dev, 30mb data on map	B-12	Z	2245	0745	0745	JH
	Appraise late data, PIREPs; complete wall map overlay	B-20	A		1	0755	
-3:45	Take overlay, temp dev, msn folder, etc. to brfg room	B-20	A	1	0750	1 '	
-3:40	Brief pilots & operations staff	B-20	A		0800	0800	1 - 4 1
-3:30		B-1.1	A	1	0830	0730	
5×199		B-12	z		0900		
	Begin met watch log; post AR board & color tags in CP	B-14	A	0000	0900	0843	DM
	Get letdown plates at briefing, add wx, give to DCOM Receive & post [Wx Scout Reports] (bad news only		A	0030			
5×199	A STATE OF THE STA	B-10	C	ASAP			
Vrbl	Receive APT pictures; deliver to CP for appraisal	B-20	A		1020		
-1:10	Rebrief pilots if necessary					1030	And
-1:00	Begin met watch in CP	B-13		0130	1070	1030	
Vrbl	Discuss APT picture with Hq SWO (HY-2, psbl	B-10				1030	ARDI
1+0:30	Prepare debriefing form (draw route, enter data, etc.)	B-15	A	 		1030	2
	***********************************		****	*****	<u> </u>	<u> </u> ++++++	*****
		B-13	1			1545	
L+0:15	Return materials from CP to weather station	B-15		1		1541	Mil
L+0:15	Complete debriefing form entries (landing ob, times)			1	1	1615	190
L+0:45	Attend pilot debriefing	B-15		ASAP	ASAP		
5XSAR	Coordinate input with DCOM after debriefing	B-15					-
	Clean briefing overlays, put weather station in order	B-12	X	1100	2000	+	+
		-	_	+	+	-	+
l			1	1	1	1	1

Leave completed checklist, debriefing form, met watch log, and all other material pertaining to the mission in the mission folder. After checking for completeness, put the folder in a manila envelope marked "BX68um Ux File" and file in safe. When no longer needed for referral, turn over to Intelligence for storage.

as of 2	3 Dec 67		2002/06/13 : CIA-RDP6 K SHIELD CHECKLIST	9 B	41R00	150002		el of		
Mission	BX6843	Mission Date 5 JAN	168 H-hour <i>05/0</i>	230 Z	<i>1130</i> L	L-hou	105106	30 Z J	<i>530</i> L	
Key Per	sonuel	DCOW Personnel	Duty Hours				e Sche			
25×4×	Pilot N	Ì	04/06 - 1700 L; 05/06.	<i>1830</i> T	Sat Ac	q T	Avlb T		erage	
Spare Pilot			04/16-0300 L; /	1			0839		DNU	
		04/08-/001;05/03-		1	 				RODN	
				7300 7 7 7 7		012 103				
<u>i</u>		-	04/11-2400 L; 05/11.	9					RODN	
			/ - L; / :				1220	RO		
			04/07-/100 L;05/00. Standby period Con	- <i> 00</i> L ntact	N4 1	3 45	1408	76	FT	
		CAPT YOUNG	05/6200-1500 L 62		Rspb1	Tim	e Due	Done	7	
H-Minus	Ac	etion	nider-ekirkleridiri kayışlarınının kokaklarılı edili erili erili edili elektrili elektrili elektrili elektrili	SOP	Indiv	(Z)	(L)	(L)	Intla	
-27:00	Start this ch	necklist		B -3	С	03/ /2330	04/	0800	Dus	
-26:00	Arrange work	schedule	maji ng 1904 ng 1902 ng mga Programmaga Anggle et 1910 T. no situang na nanang ng mga kanta ng paggan manangkat alb	B-4	A	04/0030	0930	0800	Duff	
-25:00	Determine API	picture schedule for	r mission day	B-10	С	0130	1030	8900		
-23:30		nder's Briefing	. Start (miles after after the control of the contr	B-1	A	0300				
2 3 3.99	Receive	Preliminary Operation	andre and a construction of the contrast to the construction of the contrast o	B-1	<u>A</u>	0330		0730	DES	
25×1A		cout call signs	Message)	B-22	A	Vrbl	Vrb1	164	M	
		C preliminary briefin	Control of the second of the s	B-2	C	0100 N/A	1000	e N/I	70/	
· · · · · · · · · · · · · · · · · · ·		ning forecast & briefinary briefing to		B-2 B-2	A	וו	 			
		eary briefing to	crews		A	1				
		ion briefing times for	on this chaoklist	B-2	A		 	15000	190	
	GEL TIPO MISS	sion bliefing times it	or this checkitst	10-2				1300	20	
251X10A	Receive	Mission Weather Dat	a)	B-6	A	0530	1430	1344	199	
-21:00			B-5	A	0530	1430	1353	SI		
	START			<u> </u>					Line	
-20:00	Prepare brief	ing acetate on wall m	nap	B-7	A	0630	1530	1500		
75-51-37 1 A	Receive	(Composite Route Da	ata via data link)	B-6	Aor B	Vrb1	Vrbl	1713	RAU	
ZĐA IA	RECEIVE	(domposite Rodeo De	iod vad dica zamy				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
9 ξ /χ4Ω	Receive	mnd (Mission Weathe	er Data update)	B6	В	0900	1800	1723	RAH	
-17:15	Receive	(Terminal Forecasts update)			В	0915	1815	1723	RAY	
-17:00	Receive Primary Alternates & Missed AR Bases		ed AR Bases	B-21	В	09\$5	1815	1400	AT 1	
						טטדיכז	1600		- Da	
-17:00	Give initial	briefing to pilots &	operations staff	B-7	В	0915	1890	1600	1010	
							 			
15.00	Receive	Wanker Mission West	then Data	B-9	В	1115	2015	4932	RAH	
2 5%9% -14:00				B-24	В	1215		2115		
		needed for monitoring		B-12	х	1200	2100	2100	TY	
25X1A	Receive	Final Operational I		B-8	В	1400	2300	2305	RAH	
-11:00	Prepare RODN	& top-off AR forecast	28	B-5	В	1515	10015	<u>0030</u>	TY	
							:	<u></u>		
							1	<u>. </u>	<u> </u>	
Cancell	ation/Postpone	ement Data: Time /	Z L Reason							
lotify	personnel as a	apppprayed For Release	2002/06/13 : CIA-RDP6	59B000	41R00	150002	:0016-4	1		